CHRISTIE

INFORMATION BULLETIN

TIPM 9.3

Applies to the Following Products			
• Roadie HD+35K	• Mirage S+16K	• Christie DS+5Kc	• Mirage W8
• RPM products	• Mirage S+20K	• Christie DS+6K	• Mirage HD8
• Cine-IPM	• Christie DW3K	• Mirage S+6K	• Matrix W4
• Roadster S+12K	• Christie DW3Kc	• Matrix S+5K	• Matrix HD4
• Roadster S+16K	• Christie DW5K	• Christie DS+8K	• DLV1920-DX
• Mirage S+14K	• Christie DW4Kc	• Mirage S+8K	• Matrix HD2
• Roadster S+ 20K	• Christie DW6K	• Christie HD5K	• Matrix HD7
• Roadster HD12K	• Christie DW6Kc	• Christie HD6K	• Christie HD3K
• Roadster HD18K	• Christie DW8K	• Christie HD5Kc	• Christie HD2Kc
• Mirage HD18	• DLV1400-DX	• Christie HD8K	• Matrix WU2
• Mirage HD12	• Matrix S+2K	• Mirage HD3	• Matrix WU5
• Mirage WU12	• Mirage S+3K	• Mirage W6	• Mirage WU3
• Mirage WU18	• Christie DS+5K	• Mirage HD6	• Mirage WU7
• Mirage S+12K	• Matrix 4000		

Prepared for: External customers, Christie personnel

This bulletin communicates changes in Ethernet communications functionality on the TIPM 9.3 (P/N: 001-100093-06) compared to the TIPM 9.2 (P/N: 001-100093-05). Due to a component discontinuation by the manufacturer, the TIPM 9.2 will not be available after February 2014 on new production or service assemblies.

TIPM 9.3 Ethernet Communication Details

The following features are available and unchanged from TIPM 9.2:

• Web interface

• Serial-over-Ethernet

• ArtNet

• SMTP trap emails

• SNMP traps

The following SNMP functionality changed in TIPM 9.3:

• The lamp on/off function is the only supported SNMP SET command.

• The lamp power and status item are the only supported SNMP GET commands.

• OIDs for support items are identical; existing MIB files still work with the SNMP console software.

• All other SNMP items are unavailable.

Technical Support

North and South America: +1-800-221-8025 or tech-support@christiedigital.com

Europe, Middle East, and Africa: +44 (0) 1189 778111 or techsupport-emea@christiedigital.com

Asia Pacific: tech-asia@christiedigital.com