
Software Release Notes

CorePlus Gen2 version 1.0.2

This document provides the changes from CorePlus Gen2 version 1.0.1 to 1.0.2.

Affected products

The following products are affected.

LED012-CP-R	LED014-CP-I
LED014-CP-R	LED019-CP-I
LED019-CP-R	LED024-CP-I
LED024-CP-R	LED030-CP-I
LED012-CP-I	LED040-CP-I

Purpose of release

The primary purpose of this release is to introduce the following features:

- Added support for the MBI5153 Reset.
- Fixed an issue with mapping for CorePlus P4.

Technical support

Technical support for Christie products is available at:

- North and South America: +1-800-221-8025 or Support.Americas@christiedigital.com
- Europe, Middle East, and Africa: +44 (0) 1189 778111 or Support.EMEA@christiedigital.com
- Asia Pacific: +65 6877-8737 or Support.APAC@christiedigital.com