
Technical Bulletin

Required optical alignments after optical assembly replacement

This bulletin provides information about the optical alignments required after an optical assembly replacement or when doing preventative maintenance.

If an optical assembly is replaced for any reason in an RGB, RBe, or RGBH projector or when doing preventative maintenance, the projector's Service Manual must be reviewed for all associated instructions for proper part replacement along with the alignments required after the part replacement. Optical assembly replacements may require alignment to be made after replacement due to a slight misalignment from the previous assembly configuration.

Failing to perform proper optical alignments after a part replacement could lead to reduced brightness and/or damaging internal projector components. If damage in the projector is caused due to failed optical alignments after part installation, any failures associated are not covered under warranty.

Affected products

These instructions apply to the following products.

- CineLife™ (Series 3) projectors
- CineLife+™ (Series 4) projectors

Accessing Service manuals from the Christie website

Follow these steps to access the projector's Service manual from the Christie website.

1. In a browser go to www.christiedigital.com.
2. Sign into the Partner Portal.
3. Search the website for the product.
4. On the product page, switch to the **Downloads** tab.
5. Expand the **Service Manuals** section and under the relevant document select the Service manual to open it.

Technical support

Technical support for Christie Cinema products is available at:

- Support.cinema@christiedigital.com
- +1-877-334-4267